



Product	Description	Pkg	Each
SitePro Central Tune Up			
IS-x-SPCTU-A (labor)	Physically clean the CPU (computer tower) interior. Update the SitePro database; delete temporary files and backup data from 2008, set up a 2009 database	1	305.00
IS-x-SPCTU-B (labor)	All above + run SitePro diagnostics and defrag hard drive	1	595.00
IS-x-SPCTU-C (labor)	All above + update to the latest licensable, computer capable, version of SitePro, review program types and database information	1	995.00
SitePro Central Setup and Software Programming			
IS-x-SPSETUP	SitePro Setup	1	1,600.00
IS-x-SPOPT	SitePro Optimization	1	4,167.00
IS-x-SPCU	Install Computer & Update SitePro	1	995.00
IS-x-SPU	Update SitePro	1	795.00
IS-x-SPCNP	Create new programs (per hour)	1	105.00
IS-x-SPOPTH	SitePro Optimization (per hour)	1	105.00
FCC License and Site Survey fees			
IS-x-SURVEY	Site Survey (Less FCC license fee)	1	1,290.00
IS-x-FCC	FCC License fee	1	510.00
E-Osmac Base Station Tune Up			
IS-x-BSTU (labor)	Update to current firmware, verify FCC license, inspect connections and verify radio signal strength	1	210.00
Field Interface Unit (FIU)			
IS-x-FIUTU (labor)	Physically clean the FIU interior, verify connector and test signal strength	1	105.00
IS-x-FIUTU (labor)	Radio FIU -All above and verify FCC license, inspect antenna connections and verify radio signal strength	1	210.00
Install Antenna Surge Protection			
Includes inline surge protector, jumper cable and grounding to existing electrical ground			
Parts included:		1	159.00
AA259BNC-6	Antenna Interface Cable x 6' long		
AA612	Antenna Surge Protector		
160635/ft	6 AWG Solid Ground Wire (per ft)		
IS-x-BSAG (labor)	Install antenna surge protection	1	105.00
Install Rain Switch - Osmac Base Station			
Install components and configure software. Parts needed: wireless rain switch, transformer and special cable assembly. What an easy way to conserve water!			
Parts included:		1	162.00
TWRS	Toro wireless sensor		
363-3514	24 VAC Transformer		
BSRS-KIT	Cable Assembly Kit		
IS-x-BSRS	Install rain switch	1	565.00
Install Rain Switch - Field Interface Unit			
Install components and configure software. Parts needed: wireless rain switch, transformer and special cable assembly. What an easy way to conserve water!			
Parts included:		1	162.00
TWRS	Toro wireless sensor		
363-3514	24 VAC Transformer		
FIURS-KIT	Cable Assembly Kit		
IS-x-FIURS (labor)	Install rain switch	1	565.00
Install SPU (Surge Protection Unit) Secondary Surge Protection			
DLPT-10G-10	Surge protector	1	101.00
IS-x-FIUSPU	Install Secondary Surge protection -Field Interface Unit	1	305.00



Product	Description	Pkg	Each
Field Controller Tune Up			
Verify communication with the central, 120/220V power, 24V outputs, inspect and tighten all wire connections, inspect components for damage, clean interior and test controller grounding			
IS-x-FCT-LTCP	Field Controller Tuneup - LTC Plus	1	185.00
IS-x-FCT-NVP	Field Controller Tuneup - Network VP	1	185.00
IS-x-FCT-N8	Field Controller Tuneup - Network 8000	1	215.00
	Add DLPT-10G-10 Surge for above (each)	1	101.00
Modem Tuning			
IS-x-MTFS (labor)	Remove, bench test, calibrate and reinstall modem. Includes labor to remove and reinstall	1	60.00
IS-x-MTSS	Bench test, calibrate and reinstall modems. You remove and you reinstall (Self serve)	1	45.00
Lightning Detection System Tune Up - ESID			
IS-x-LSC-ESID	Lightning Sensor Calibration - Esid -Factory Service	1	2,175.00
IS-x-LSRR (labor)	Labor to remove and reinstall	1	305.00
Shipping to AZ	Shipping, special carton, insurance	1	92.50
Shipping from AZ	Shipping, special carton, insurance	1	92.50
Lightning Detection System Tune Up - Strike Guard			
IS-x-LSC-SG	Lightning Sensor Calibration - Esid - Factory Service	1	1,715.00
IS-x-LSRR (labor)	Labor to remove and reinstall	1	305.00
Shipping to AZ	Shipping, special carton, insurance	1	92.50
Shipping from AZ	Shipping, special carton, insurance	1	92.50
Lightning Warning System Tune Up			
Clean and inspect all connections, test for proper system operation			
IS-x-LWSTU (labor)	Lightning Warning Siren Tune Up (each) battery	1	105.00
	Replacement battery	1	29.00
	desiccant	1	6.00
IS-x-LWSTU-S	ZDpLightning Warning Siren Tune Up (each) battery	1	115.00
	Replacement battery	2	58.00
	desiccant	2	12.00
Wire Tracking & Irrigation Repair Services			
IS-x-WTS	Wire Tracking (per hour)	1	105.00
IS-x-LABOR	Irrigation Repair (per hour)	1	105.00
IS-x-LABOR-WH	Irrigation Service Weekend & Holiday (per hour)	1	165.00
IS-x-TRAVEL	Travel Rate (per hour)	1	65.00
IS-x-ZONE1	Irrigation Service (Zone 1)	1	53.00
IS-x-ZONE2	Irrigation Service (Zone 2)	1	85.00
IS-x-ZONE3	Irrigation Service (Zone 3)	1	105.00
IS-x-ZONE4	Irrigation Service (Zone 4)	1	130.00



All prices subject to change