

Water Fountain Service Program

Let us help you save time, save resources and save money.



Otterbine™ Fountain Tune Up

Otterbine™ Water Fountains are the industry's premium water fountains. A little care every three to five years will make them last a long time. The manufacture recommends at a minimum every three years each unit should have "Service Plan A" which includes an oil change, installing new oil plugs, performing electrical reading on windings and a cleaning of the unit. Every five years the manufacturer recommends "Service Plan B" which includes all the above along with a bearing wear check and/or replacement, installation of new seals and o-rings and a complete unit teardown and cleaning. Let our factory certified technicians tune up your fountains before next season!

CONCEPT 2 UNITS:

IS-X-OTR-C2-SRVA 1-5Hp Concept 2 Plan A (labor)..... \$315
Parts kit estimate* \$111

IS-X-OTR-C2-SRVB 1-5Hp Concept 2 Plan B (labor)..... \$425
Parts kit estimate* \$170

CONCEPT 3 UNITS:

IS-X-OTR-C3-SRVA 1-5Hp Concept 3 Plan A (labor)..... \$345
Parts kit estimate* \$73

IS-X-OTR-C3-SRVB 1-5Hp Concept 3 Plan B (labor)..... \$465
Original motor parts kit estimate* \$127
Current motor parts kit estimate* \$248

IS-X-OTR-ENV (Environmental Disposal Fee) \$25
Pond removal/install (side tether) \$195
Pond removal/install (bottom) \$325
Trucking fee (round trip, per unit) \$50
Fuel surcharge (round trip per customer) \$20
New Anchors and Tethers..... \$58
Power control panel inspection and cleaning \$85
Storage rate (week) \$8



NOTE:

In all cases travel and/or zone charges are additional. Environmental Disposal Fees are additional. Parts and/or labor required beyond parts kits shown above are additional.

*Parts prices subject to change without notice.